

Recall Number	Model Name/Model	Recall Class	Date Initiated	Date Resolved	Resolving Manufacturer	Reason for Recall
Z-2341-2008	LIFEPAK CR Plus	1	08-28-2008	09-15-2008	Physio Control Inc.	This recall is being contained due to the device being configured with the incorrect software for semi-automatic cardio arrest emergency mode. The software for a cardio arrest emergency mode will require that the user press the shock button instead of automatically delivering a shock as per the normal operation of the fully automatic device.
Z-1238-2007	Escher-Mix 2400	1	08-27-2007	09-27-2007	Bana Corporation	A software defect could allow up to 50mL of extra volume being added to a TPN solution.
Z-1081-2007	Colligera 2.3 OX and 3 C&E Volumetric Infusion Pumps	1	08-26-2007	07-16-2007	Baxter Healthcare Corp.	A software anomaly is causing newly upgraded Colligera Tris (16310/897/4000) and stop the infusion. This occurs during user programming with all three channels simultaneously infusing fluids. In reported cases the pump stopped infusing and the user was unable to restart the infusion. (On May 11 2007) Also notified companies that the device software with Adjuvant of the device would be discontinued.
Z-0854-2007	LADAR8000	1	02-21-2007	08-05-2007	Alcon Refractive Horizons Inc.	Device Malfunction-The self-test software may allow a self-test to clear a previously detected low battery condition. If this occurs the device may be unable to deliver a defibrillation shock which could result in failure to resuscitate a patient.
Z-0380-2007	Uline MED-8000 with Selfly	1	02-17-2007	08-09-2007	Defitech LLC	Device Malfunction-The self-test software may allow a self-test to clear a previously detected low battery condition. If this occurs the device may be unable to deliver a defibrillation shock which could result in failure to resuscitate a patient.
Z-0581-2007	Revstar AED-Defibech	1	02-17-2007	08-09-2007	Defitech LLC	Device Malfunction-The self-test software may allow a self-test to clear a previously detected low battery condition. If this occurs the device may be unable to deliver a defibrillation shock which could result in failure to resuscitate a patient.
Z-0641-05	SAMARTAN	1	02-14-2005	02-24-2005	Heraeus Technologies Inc.	Four warning and start beeps occur before a shock can be delivered to the patient. This is reportedly due to slow capacitor charging rates which are interpreted by the AED as a low battery condition.
Z-0218-05	DEBELLATO RS	1	04-02-2003	11-30-2004	Tooth Blastech Inc.	A software upgrade was released by the firm for its AAU-800 T unit connected to the DEBELLATO RS. The upgrade was intended to correct a software bug that caused the unit to stop working. The unit is used in conjunction with the Model 8840 X-Ray Film Clinician Programmer users may have mistakenly entered a periodic bolus interval into the minutes field of the software. This issue is limited to programming the SynchroMed El pumps.
Z-1024-04	8070 Software Card Version AA 02	1	08-24-2004	09-29-2004	Medtronic Inc Neurologist & Spinal Division	Software defect: The software for the 8070 software card version AA 02 contains a software bug that causes the software to stop working. The unit is used in conjunction with the Model 8840 X-Ray Film Clinician Programmer users may have mistakenly entered a periodic bolus interval into the minutes field of the software. This issue is limited to programming the SynchroMed El pumps.
Z-1021-04	COBAS Gil interface	1	02-05-2004	07-20-2004	Roche Diagnostics Corp.	The Roche COBAS interface driver for the Tscan software may assign sample results to the wrong patient.
Z-0382-04	Tscan clinical workstation; 10-410 Tscan back and Roche catalog number 0258535001.	1	08-05-2004	07-20-2004	Roche Diagnostics Corp.	Tscan software has the potential to match the patient with a different patient's test results.
Z-1001-04	Tscan clinical workstation; 10070 (front end) catalog number 0258535001.	1	08-05-2004	07-20-2004	Roche Diagnostics Corp.	Tscan software has the potential to match the patient with a different patient's test results.
Z-1000-04	Tscan clinical workstation; 415 Tscan front end Roche catalog number 0258535001.	1	08-05-2004	07-20-2004	Roche Diagnostics Corp.	Tscan software has the potential to match the patient with a different patient's test results.
Z-0007-04	Myria Laboratory	1	08-12-2003	07-20-2004	Myria Healthcare Systems	Software defect: Clinical Laboratory result filing quality assurance users filing directly to a patient's chart without different patient's test results.
Z-1022-04	Tscan Genesis	1	08-05-2004	07-20-2004	Tscan U S Inc	Software defect: The software for the Tscan Genesis has the potential to match the patient with a different patient's test results.
Z-1857-2009	COBA Computed Tomography X-Ray System	2	04-14-2009	07-07-2009	Hitachi Medical Systems America Inc	Incorrect scale on image: A software error can occur if two (2) different Fluid-to-View (FV) settings are registered in a single image. The error can occur if the software is not properly configured to be displayed with the wrong scale factor resulting in anatomical measurements incorrect.
Z-1652-2009	ECLIOS Computed Tomography X-Ray System	2	04-14-2009	07-07-2009	Hitachi Medical Systems America Inc	Incorrect scale on image: A software error can occur if two (2) different Fluid-to-View (FV) settings are registered in a single image. The error can occur if the software is not properly configured to be displayed with the wrong scale factor resulting in anatomical measurements incorrect.
Z-1862-2009	CardiAssist	2	04-09-2009	07-07-2009	Cardiometrics Incorporated	Software defect: The software for the CardiAssist has the potential to match the patient with a different patient's test results.

Z-1576-2009	GEHMI OXL	Philips Medical Systems (Cleveland) Inc	07-05-2009	07-05-2009	Philips Medical Systems (Cleveland) Inc	A software anomaly in the Tuneloc software for the firm's Brilliance CT scanners was discovered. The same software anomaly was subsequently determined to be present in the Tuneloc software for the firm's Brilliance CT scanners. The potential for data to be lost during reconstruction of images in which slices can either be expanded or interleaved based upon their slices ID.
Z-1802-2009	CEMRI RAPTOR	Philips Medical Systems (Cleveland) Inc	07-06-2009	07-06-2009	Philips Medical Systems (Cleveland) Inc	A software anomaly in the Tuneloc software for the firm's Brilliance CT scanners was discovered. The same software anomaly was subsequently determined to be present in the Tuneloc software for the firm's Gemini PET/CT units. The software defect results in images in which slices can either be expanded or interleaved based upon their slices ID.
Z-1578-2009	PHILIPS PLUS COMPUTED TOMOGRAPHY SYSTEM	Philips Medical Systems (Cleveland) Inc	07-05-2009	07-05-2009	Philips Medical Systems (Cleveland) Inc	A software anomaly in the Tuneloc software for the firm's Brilliance CT scanners was discovered. The same software anomaly was subsequently determined to be present in the Tuneloc software for the firm's Gemini PET/CT units. The software defect results in images in which slices can either be expanded or interleaved based upon their slices ID.
Z-1549-2009	GE Healthcare PACS software	GE Healthcare Integrated IT Solutions	07-01-2009	07-01-2009	GE Healthcare Integrated IT Solutions	There is a potential safety issue associated with the use of DICOM Centricity PACS software related to configuration of DICOM Software. Software may not appear in brain scans and software may not appear in brain scans and software may not appear in brain scans.
Z-1582-2009	BRILLIANCE VOLUME	Philips Medical Systems (Cleveland) Inc	06-29-2009	06-29-2009	Philips Medical Systems (Cleveland) Inc	Software anomaly: An artifact may appear in brain scans and software may not appear in brain scans and software may not appear in brain scans.
Z-1439-2009	GenVue Chart	Philips Healthcare Inc.	05-27-2009	05-27-2009	Philips Healthcare Inc.	Software anomaly: Software anomaly can occur when the software is attempting to play an audio file at which time the system software may cause the system to freeze due to an interaction in the alarm system.
Z-1401-2009	Paronome Patient Monitoring Network	Medway US USA Inc 4th District Patients Monitoring	05-27-2009	05-27-2009	Medway US USA Inc 4th District Patients Monitoring	A software anomaly in the Paronome Patient Monitoring Network software may cause the system to freeze due to an interaction in the alarm system.
Z-1391-2009	Centricity Laboratory	GE Healthcare Integrated IT Solutions	05-15-2009	05-15-2009	GE Healthcare Integrated IT Solutions	A software anomaly in the Centricity Laboratory software may cause the system to freeze due to an interaction in the alarm system.
Z-1232-2009	GE PRO CLINICAL INFORMATION CENTRAL STATION	GE Medical Systems Information Technology	05-04-2009	05-04-2009	GE Medical Systems Information Technology	GE Healthcare is aware of a potential network time issues with the GE PRO Clinical Information Central Station software. These issues may impact patient safety.
Z-1002-2009	GE QUASAR NUCLEAR MEDICINE SYSTEM	GE Medical Systems LLC	04-21-2009	04-21-2009	GE Medical Systems LLC	GE Healthcare has recently become aware of excessive pressure applied by the collimator pressure sensitive cover of the GE QUASAR Nuclear Medicine System. This may impact patient safety. It was reported at a customer site that the pressure used to activate the Pressure Sensitive Device (PSD) should be lowered and that the body contouring software requires correction to prevent this.
Z-1002-2009	GE QUASAR NUCLEAR MEDICINE SYSTEM	GE Medical Systems LLC	04-21-2009	04-21-2009	GE Medical Systems LLC	GE Healthcare has recently become aware of excessive pressure applied by the collimator pressure sensitive cover of the GE QUASAR Nuclear Medicine System. This may impact patient safety. It was reported at a customer site that the pressure used to activate the Pressure Sensitive Device (PSD) should be lowered and that the body contouring software requires correction to prevent this.
Z-1002-2009	GE QUASAR NUCLEAR MEDICINE SYSTEM	GE Medical Systems LLC	04-21-2009	04-21-2009	GE Medical Systems LLC	GE Healthcare has recently become aware of excessive pressure applied by the collimator pressure sensitive cover of the GE QUASAR Nuclear Medicine System. This may impact patient safety. It was reported at a customer site that the pressure used to activate the Pressure Sensitive Device (PSD) should be lowered and that the body contouring software requires correction to prevent this.
Z-0988-2009	COZMO INCLUSION PUMP WITH COZMONITOR	Smiths Medical MD Inc	04-16-2009	04-16-2009	Smiths Medical MD Inc	Smiths Medical has become aware of a display irregularity with the COZMO Inclusion Pump with Cozmonitor. There have been 1700 containing Model 1800 software. There have been adverse events reported that the amount of Extended Bolus delivered was not accurately displayed by the Pump. The amount of Extended Bolus displayed on the Pump Home Screen 2 and in the Bolus Summary Report is less than what was delivered.
Z-0989-2009	COZMO INCLUSION PUMP WITH COZMONITOR	Smiths Medical MD Inc	04-16-2009	04-16-2009	Smiths Medical MD Inc	Smiths Medical has become aware of a display irregularity with the COZMO Inclusion Pump with Cozmonitor. There have been 1700 containing Model 1800 software. There have been adverse events reported that the amount of Extended Bolus delivered was not accurately displayed by the Pump. The amount of Extended Bolus displayed on the Pump Home Screen 2 and in the Bolus Summary Report is less than what was delivered.
Z-1084-2009	GELL-Dyn Pump	Abbott Laboratories	04-10-2009	04-10-2009	Abbott Laboratories	Carryover failures in software revisions 1.0M and 2.0M result in elevated PLT background count.
Z-0989-2009	Transmembrane Health System	Cardinal Health Inc	04-07-2009	04-07-2009	Cardinal Health Inc	Internal testing has identified several scenarios where unexpected System (lockup shutdowns or system errors would occur) that could be caused by software anomalies. These anomalies can be corrected by installing the Version 6.0.0.5 software updating the Audio Driver and updating to the Service Pack 3. Additionally improper wiring could cause the coding unit to fail.

Z-0460-2008	GE Celerity Workstation	2 08-25-2008	12-12-2008	GE Healthcare Integrated IT Solutions	Software anomalies result in patient safety issues involving patient jacket contact intermittently becoming unintentionally out of sync with the patient's movement. The software does not check the Study Data Time of the exam on the image list bar when they may interpret this bar.
Z-0456-2009	Celerity Personal (Formerly Quantitative System - Alert and Reminder)	2 08-25-2009	12-09-2008	GE Healthcare Integrated IT Solutions	Software anomalies in the Alert and Reminder feature could result in a patient safety issue. The software does not check the bar below the desired choice is selected and an inconsistent color may be displayed for the same element across a set of work stations.
Z-0195-2009	GE AUDAERA	2 08-12-2008	11-12-2008	Cardinal Health Inc	CSI Acacia system requires a system software update due to missing essential (NEMO) functions.
Z-0213-2009	Noble Care Server used in Web Viewer and Cellular Receiv	2 07-16-2009	11-05-2008	GE Healthcare	Issue 1 - Possible failure of DICOM Pro output alarm: Requests for tables (requests from Noble Care) are not processed. This excessive memory consumption may lead to potential loss of audio at the CIC or a system reset or reboot. Issue 2 - Mobile Care software/Mobile Viewer Mobile Care software. A software bug may result in plotting from an incorrect reagent pack and/or assigning calibration curve parameters incorrectly.
Z-0162-2009	Receiv	2 08-24-2008	10-22-2008	Roche Diagnostics Corp.	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0164-2009	Vision RV Software	2 08-02-2008	10-22-2008	Vision Medical Systems Oncology Systems	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0086-2009	Low Arches Therapy	2 08-19-2008	10-07-2008	Hill-Rom Manufacturing Inc.	Functionality of the software is not correct. The software does not allow the patient to be examined on the patient movement alarm to function correctly.
Z-1751-2008	Siemens syngo Dynamic	2 07-08-2008	09-29-2008	Siemens Medical Solutions USA, Inc.	Functionality of the software is not correct. The software does not allow the patient to be examined on the patient movement alarm to function correctly.
Z-1882-2008	GE Definition 8000	2 03-07-2008	09-25-2008	GE Healthcare	Functionality of the software is not correct. The software does not allow the patient to be examined on the patient movement alarm to function correctly.
Z-1822-2008	GE Definition 8000	2 03-07-2008	09-25-2008	GE Healthcare	Functionality of the software is not correct. The software does not allow the patient to be examined on the patient movement alarm to function correctly.
Z-2489-2009	NicoleOne 5.302.1 Software	2 08-10-2009	09-20-2008	Cardinal Health Neuroscience	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-1812-2008	Siemens TPS	2 02-10-2008	09-20-2008	Vision Medical Systems Oncology	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-2329-2008	Siemens TPS	2 02-10-2008	09-20-2008	Vision Medical Systems Oncology	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-2229-2008	Siemens TPS	2 02-10-2008	09-20-2008	Vision Medical Systems Oncology	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-2184-2008	Siemens TPS	2 02-10-2008	09-20-2008	Vision Medical Systems Oncology	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-2308-2008	Siemens TPS	2 02-10-2008	09-20-2008	Vision Medical Systems Oncology	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-2185-2008	Siemens TPS	2 02-10-2008	09-20-2008	Vision Medical Systems Oncology	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-2188-191	Siemens TPS	2 02-10-2008	09-20-2008	Vision Medical Systems Oncology	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-2188-2008	Siemens TPS	2 02-10-2008	09-20-2008	Vision Medical Systems Oncology	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-2188-191	Siemens TPS	2 02-10-2008	09-20-2008	Vision Medical Systems Oncology	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-2038-2008	Siemens TPS	2 02-10-2008	09-20-2008	Vision Medical Systems Oncology	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-2037-2008	Siemens TPS	2 02-10-2008	09-20-2008	Vision Medical Systems Oncology	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-2104-2008	Siemens TPS	2 02-10-2008	09-20-2008	Vision Medical Systems Oncology	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-2039-2008	Siemens TPS	2 02-10-2008	09-20-2008	Vision Medical Systems Oncology	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-2039-2008	Siemens TPS	2 02-10-2008	09-20-2008	Vision Medical Systems Oncology	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-2039-2008	Siemens TPS	2 02-10-2008	09-20-2008	Vision Medical Systems Oncology	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.

Z-0506-2009	Vevo Healthcare Transcranial Doppler (TCD) System	2 01-06-2009	04-07-2009	Cardinal Health Inc	Recent testing has identified several event creation where unexpected System lockups shutdowns or system errors would restrict the Sonora unavailable for use until the Sonora can be restarted. These issues can be corrected by installing the software update to the Sonora. The software update will be working to XP Service Pack 3. Additionally manually saving could cause the config file to not save.
Z-1040-2009	OCA and OCA Software	2 11-08-2008	03-24-2009	Lectra Microsystems Inc.	A change in the software to open up the software architecture for use with other software. The software update will be working to XP Service Pack 3. Additionally manually saving could cause the config file to not save.
Z-1050-2009	ED PrepStein System	2 08-26-2008	03-19-2009	GE Diagnostic Systems	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0691-2009	Edges treatment planning system	2 11-21-2008	02-20-2009	Vision Medical Systems Oncology Systems	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0624-2009	O-ARM(R)	2 11-27-2007	02-04-2009	Medtronic Navigation Inc.	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-3052-2009	Imnova 2100Q	2 12-09-2008	01-23-2009	GE Medical Systems	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-3054-2009	Imnova 2100Q	2 12-09-2008	01-23-2009	GE Medical Systems	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-3013-2009	Imnova 2100Q	2 01-30-2008	01-21-2009	GE Medical Systems	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0474-2009	Imnova 2100Q	2 01-30-2008	01-21-2009	GE Medical Systems	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0475-2009	Imnova 2100Q	2 01-30-2008	01-21-2009	GE Medical Systems	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0475-2009	Imnova 2100Q	2 01-30-2008	01-21-2009	GE Medical Systems	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0475-2009	Imnova 2100Q	2 01-30-2008	01-21-2009	GE Medical Systems	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0475-2009	Imnova 2100Q	2 01-30-2008	01-21-2009	GE Medical Systems	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0729-2009	Dynamics FC 500 Flow System with CVP Software	2 10-11-2007	01-13-2009	Beckman Coulter Inc	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0870-2009	Celerity Web	2 12-12-2008	01-12-2009	GE Healthcare Integrated IT Solutions	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0608-2009	CVRX Computed Tomography CVP Acquisition Software	2 11-05-2008	01-09-2009	Hologic Medical Systems America Inc	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0455-2009	CVP Acquisition Software	2 08-01-2007	01-07-2009	Beckman Coulter Inc	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0270-2009	Sonastom 40 X-Ray System	2 08-03-2008	01-05-2009	Siemens Medical Solutions USA Inc	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0271-2009	Sonastom 40 X-Ray System	2 08-03-2008	01-05-2009	Siemens Medical Solutions USA Inc	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0285-2009	Sonastom 40 X-Ray System	2 08-03-2008	01-05-2009	Siemens Medical Solutions USA Inc	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0322-2009	GE Healthcare Ultrasound System	2 04-02-2008	01-05-2009	GE Healthcare	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0323-2009	Philips Ultrasound System	2 08-12-2008	12-31-2008	Philips Medical Systems	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0323-2009	Philips Ultrasound System	2 08-12-2008	12-31-2008	Philips Medical Systems	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0472-2009	GE Healthcare Ultrasound System	2 08-22-2008	12-31-2008	GE Healthcare Integrated IT Solutions	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0469-2009	Hologic	2 09-24-2008	12-29-2008	Hologic Inc.	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.
Z-0444-2009	Videra N/P Nucleic Sample Preparation	2 08-30-2007	12-16-2008	Beckman Coulter Inc	Software anomalies when the Vort software might result in a misadministration (under-dose). The software does not correctly interpret the number causing field parameters having decimal values to be incorrect.

Z-1939-2008	BD Biosciences BD QSOX Software Versions 4.0.1 to 5.0.2	2/04/05/2007	08-16-2008	BD Biosciences	When this file is selected, the software automatically applies compensation to this file and all subsequently acquired files.
Z-1915-2008	MDSAQ Version 1.0, med 1.4	2/02-14-2008	08-16-2008	Imasec Medical Systems Inc.	Software issue may result in change to intended treatment field potentially resulting in mistreatment.
Z-1842-2008	Varian Medical Systems On-Board System Versions 10.15 and 10.05	2/01-03-2008	08-15-2008	Varian Medical Systems Oncology System	If used with a third party applicator, therapy treatment planning dependent on measurement may occur because of a misalignment.
Z-1929-2008	Chemistry 300 Flow Software with Data Injections Instrument	2/08-20-2007	08-08-2008	Beckman Coulter Inc	Labeling provided by two integrated software systems are not clear enough to avoid potential demographic and sample type mismatches under certain conditions.
Z-1859-2008	Hipp-Definition 720 MultiLeaf 3D US Application	2/01-30-2008	08-02-2008	Varian Medical Systems Oncology System	Date Calculation Error: Software anomaly may result in failure of a MLC leaf to open and potentially resulting in failure of a MLC leaf to close and potentially resulting in failure of a MLC leaf to open and potentially resulting in failure of a MLC leaf to close.
Z-1138-2008	Siemens Medical Solutions US MAGNETOM MR Systems	2/12-06-2007	08-29-2008	Siemens Medical Solutions USA, Inc.	Inaccurate results: A software bug may cause inaccurate wall position abnormality reports, which may be displayed.
Z-0881-2008	ADUSION Diagnosis Ultrasound System	2/09-25-2007	04-24-2008	Siemens Medical Solutions USA, Inc.	Software error: The software may not display the PAL measurement data when the PAL measurement data is displayed.
Z-0919-2008	Bioplex 2200	2/11-13-2007	04-22-2008	Bio-Rad Laboratories Inc	Incorrect values: An error was found in the Bioplex 2200 software that may affect the results of the software when using software that is not the software that was used to create the software.
Z-1949-2008	Agfa IMPAX Software Management System	2/02-14-2008	03-31-2008	AGFA Corp.	Data Sheet: Some values may be identical between the lot numbers of the software and the software that was used to create the software.
Z-0971-2008	Verano Image Analysis System (VIA)	2/08-20-2007	03-18-2008	Verano Medical Systems Inc	Software error: The software may not display the PAL measurement data when the PAL measurement data is displayed.
Z-0919-2008	MuSiSET	2/09-08-2007	03-04-2008	BD Biosciences	Incorrect results: Software error results in inaccurate display of results. If the user adjusts the lymph gate or the function (as described in the software manual) for the software, the software may not display the PAL measurement data when the PAL measurement data is displayed.
Z-0134-2008	Sentry Pro Medical Software System	2/08-14-2007	02-26-2008	Smith Medical MD Inc.	Software error: The software may not display the PAL measurement data when the PAL measurement data is displayed.
Z-0919-2008	atVine S Software System	2/09-20-2007	02-21-2008	Inuitive Surgical Inc.	Software error: The software may not display the PAL measurement data when the PAL measurement data is displayed.
Z-0719-2008	ACUSON Diagnostic System	2/09-16-2007	02-15-2008	Siemens Medical Solutions USA, Inc.	Software error: The software may not display the PAL measurement data when the PAL measurement data is displayed.
Z-0720-2008	VARIS PRT Exchange	2/10-02-2007	02-15-2008	Varian Medical Systems Inc	Software error: The software may not display the PAL measurement data when the PAL measurement data is displayed.
Z-0816-2008	Precedence 30T System	2/08-28-2007	02-08-2008	Phillips Nuclear Medicine	Software error: The software may not display the PAL measurement data when the PAL measurement data is displayed.
Z-0654-2008	Varian RPM System version 1.7.3	2/08-26-2007	01-29-2008	Varian Medical Systems Inc	Software error: The software may not display the PAL measurement data when the PAL measurement data is displayed.
Z-0827-2008	RealSoft	2/11-14-2007	01-28-2008	Baxter Healthcare Ronal Div	Software error: The software may not display the PAL measurement data when the PAL measurement data is displayed.
Z-0528-2008	RealSoft	2/11-14-2007	01-28-2008	Baxter Healthcare Ronal Div	Software error: The software may not display the PAL measurement data when the PAL measurement data is displayed.
Z-0589-2008	Hoona LIFESD	2/11-07-2007	01-24-2008	Hoona Medical	Software error: The software may not display the PAL measurement data when the PAL measurement data is displayed.

Z-2103-2008	Siemens Medical Solutions USA, Inc	2/05-15-2008	08-17-2008	Siemens Medical Solutions USA, Inc	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-2101-2008	Siemens Medical Solutions USA, Inc	2/05-15-2008	08-17-2008	Siemens Medical Solutions USA, Inc	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-2102-2008	Siemens Medical Solutions USA, Inc	2/05-15-2008	08-17-2008	Siemens Medical Solutions USA, Inc	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-2100-2008	Siemens Medical Solutions USA, Inc	2/05-15-2008	08-17-2008	Siemens Medical Solutions USA, Inc	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-1811-2008	Inuitive Surgical Inc.	2/04-18-2008	08-17-2008	Inuitive Surgical Inc.	The firm initiated a recall of a specific, Revoire Software Ver. 1.0 Kit, which was released for distribution in a non-validated format.
Z-2006-2008	Boston Scientific Corporation	2/05-02-2008	08-17-2008	Boston Scientific Corporation	The LIFEPAK 12 defibrillator / monitor with software version 1.00 has an increase in likelihood for an incorrect Shock check decision. When Auto Analyze is set to On in AED mode the device initiates the SAS analysis immediately (ie waiting period or warning prior to anal).
Z-1804-2008	LIFEPAK 12 defibrillator/ monitor	2/04-16-2008	08-16-2008	Physix Control Inc.	The LIFEPAK 12 defibrillator / monitor with software version 1.00 has an increase in likelihood for an incorrect Shock check decision. When Auto Analyze is set to On in AED mode the device initiates the SAS analysis immediately (ie waiting period or warning prior to anal).
Z-1805-2008	LIFEPAK 20 defibrillator/ monitor	2/04-16-2008	08-16-2008	Physix Control Inc.	The LIFEPAK 20 defibrillator / monitor with software version 1.00 has an increase in likelihood for an incorrect Shock check decision. When Auto Analyze is set to On in AED mode the device initiates the SAS analysis immediately (ie waiting period or warning prior to anal).
Z-2182-2008	GE Connectivity Software System	2/06-11-2008	08-16-2008	GE Healthcare Integrated IT Solutions	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-2204-2008	Stryker Stryker Stryker	2/06-01-2008	08-16-2008	Inuitive Surgical Inc.	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-2203-2008	CAS Medical Systems Inc.	2/06-24-2008	08-16-2008	CAS Medical Systems Inc.	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-2211-2008	GE Healthcare Software System	2/10-01-2007	08-16-2008	GE Healthcare	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-2210-2008	GE Healthcare Software System	2/10-01-2007	08-16-2008	GE Healthcare	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-1946-2008	AGFA Corp.	2/05-14-2007	08-11-2008	AGFA Corp.	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-1842-2008	AGFA Corp.	2/05-14-2007	08-11-2008	AGFA Corp.	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-1312-2008	Stryker Endoscopy Ultra (USC)	2/02-15-2008	08-11-2008	Stryker Endoscopy	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-2231-2008	ABBOTT LABORATORIES LABORATORIES	2/05-23-2008	08-11-2008	Abbott Laboratories Inc.	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-2217-2008	Datex Ohmeda Inc. Software System	2/05-20-2008	08-11-2008	Datex Ohmeda Inc.	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-1826-2008	GE Healthcare Software System	2/05-06-2008	08-02-2008	GE Healthcare	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-1776-2008	Pride Mobility Products Corp.	2/04-11-2008	08-27-2008	Pride Mobility Products Corp.	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-1640-2008	Siemens Medical Solutions USA, Inc	2/03-28-2008	08-24-2008	Siemens Medical Solutions USA, Inc	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-1695-2008	AMO NLS-Scan Workfront System 4.65	2/11-17-2008	08-20-2008	AMO INC	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.
Z-1789-2008	Siemens Software System	2/10-03-2007	08-20-2008	Siemens Medical Solutions USA, Inc	Software - Under certain circumstances the partial image may be overwritten which may lead to incorrect dosage.

Z-0937-2007	Merlin PCS Programmer	2 10-06-2008	12-19-2006	St. Jude Medical CRMG	St. Jude Medical has identified a low-frequency anomaly in the software used in the APS III Medtronic 3500/3510 and Merlin PCS Model 3650 programmers that can lead to incorrect reporting of battery voltage expected battery longevity and Elective Replacement Indicator (ERI) status.
Z-0938-2007	Reche Modular Drive	2 11-03-2006	11-29-2006	Data Innovations, Inc.	Software of modular driver may incorrectly report patient results as Quality Control Benefits.
Z-0939-2007	Reche Cobas Sizer	2 11-03-2006	11-29-2006	Data Innovations, Inc.	Micro-identification of a seal or protocol is added to an existing worldfile that the tube location is not specified the CXP Acquisition software will run the last specified tube through the tube rack and may cause a false identification of the product of the sample.
Z-0940-2007	Cyromex Flow Cytometry System	2 07-26-2006	11-21-2006	Beckman Coulter, Inc.	Software of flow cytometer may incorrectly report patient results as Quality Control Benefits.
Z-1519-06	ADVA Centaur CP System	2 09-04-2006	09-23-2006	Boyer Healthcare LLC (Diagnostic Division)	Micro-identification of a seal or protocol is added to an existing worldfile that the tube location is not specified the CXP Acquisition software will run the last specified tube through the tube rack and may cause a false identification of the product of the sample.
Z-1502-06	LIFEPAK	2 08-30-2006	09-13-2006	Medtronic Emergency Response Systems, Inc.	Devices with x86 SYSTEM TO AC POWER message when the BATTERY CONNECT TO AC POWER message when the system is on battery (DC) battery power and may shut down without a warning.
Z-1382-06	Gammahed software	2 05-01-2006	08-10-2006	Varian Medical Systems	Software control program for a medical device used in radiation treatment may cause practitioners to incorrectly administer the treatment when the software is not properly updated.
Z-1383-06	Gammahed software	2 05-01-2006	08-10-2006	Varian Medical Systems	Software control program for a medical device used in radiation treatment may cause practitioners to incorrectly administer the treatment when the software is not properly updated.
Z-1372-06	VARIS Version 8.6	2 09-20-2005	08-05-2006	Varian Medical Systems Oncology System	A software anomaly may occur which can lead to patient treatment with the wrong field. The anomaly is reported only to the software when the software version (8.3022) is used with Elekta SRS.
Z-1310-06	MONITOR	2 06-21-2006	08-02-2006	Edwards Lifesciences LLC	Edwards Lifesciences Vigilance monitors with software version 5.3 or earlier may improperly cause the monitor to deliver power to the Continuous Output (CO) port without the user's authorization and thermal damage to the CO catheter and separate patient injury.
Z-1317-06	Smart Gas and Electrolyte & Metabolite Co-Ox	2 06-17-2005	08-02-2006	Radiometer America Inc	Software defect: pO2 and pCO2 sample test results run on the firm's ABL700/800 Series Blood Gas Analyzers are not being properly flagged during the sample calibration phase.
Z-1318-06	Smart Gas and Electrolyte & Metabolite Co-Ox	2 06-17-2005	08-02-2006	Radiometer America Inc	Software defect: pO2 and pCO2 sample test results run on the firm's ABL700/800 Series Blood Gas Analyzers are not being properly flagged during the sample calibration phase.
Z-1305-06	Tractor	2 04-06-2005	07-28-2006	Kensley Mark Corp	Alarm activation-A priming issue involving the flow control unit due to a software problem has caused false positive Extractions. Use of this product may result in a false positive Extractions. Minimum of 100-150 ml of extractions should be performed after extractions.
Z-1822-06	Radiance STAT Analyzer	2 03-02-2005	07-27-2006	Radiometer America Inc	Software anomaly: Data generated by blood gas equipment did not correlate with data shown in the Radiance Data Management System.
Z-1270-06	GammaWin	2 05-01-2005	07-27-2006	Varian Medical Systems	Medical device software for brachytherapy may cause erroneous data to be recorded and affect patient radiation history report and the output step size may lead to a misadministration. If treatment data is entered manually.
Z-1268-06	GammaWin	2 05-01-2005	07-27-2006	Varian Medical Systems	Medical device software for brachytherapy may cause erroneous data to be recorded and affect patient radiation history report and the output step size may lead to a misadministration. If treatment data is entered manually.
Z-1161-06	OBSERVA	2 03-28-2008	08-22-2008	bioMérieux Inc	Medical device software for brachytherapy may cause erroneous data to be recorded and affect patient radiation history report and the output step size may lead to a misadministration. If treatment data is entered manually.
Z-1147-06	LADAR/Excimer Laser System	2 08-01-2005	06-21-2006	Alcon Laboratories Inc.	Software anomaly: A software defect in the referenced software can cause a size indicator reference line to be in the wrong horizontal reference line will impact compensation for affixing surgical outcomes.
Z-1103-06	MIRAP-7000	2 03-17-2006	06-10-2006	Heath Medical Systems America, Inc	Software anomaly: A software defect in the referenced software can cause a size indicator reference line to be in the wrong horizontal reference line will impact compensation for affixing surgical outcomes.
Z-1104-06	ARIS Allaire genetic Imaging Device	2 04-28-2005	06-10-2005	Heath Medical Systems America, Inc	Software anomaly: A software defect can cause the slice line measurement (MFP) with the protocol for patient diagnosis.
Z-1099-06	CHAR-CT Scan P3 (PET/CT)	2 02-21-2005	06-03-2006	Siemens Medical Systems America, Inc	The device has a software anomaly which causes blank images to be created during Multiphase Reconstruction processing or incorrect patient identification, timing error in which a reference slice is improperly selected.

Z-0850-2007	ASCHTECT 2000	2 04-30-2007	08-19-2007	Abbott Laboratories Inc	One or more of four software issues: 1) calculation error for the ASCHTECT 2000 software. 2) Software update 2) The system configuration option Run controls onboard requesting by the KIT does not function correctly for assays requiring a standard sample dilution. 3) Inconsistent data may be missing from the Architect system. 4) Critical Error.
Z-0851-2007	ARCHTECT 2000R	2 04-30-2007	08-19-2007	Abbott Laboratories Inc	One or more of four software issues: 1) calculation error for the ASCHTECT 2000 software. 2) Software update 2) The system configuration option Run controls onboard requesting by the KIT does not function correctly for assays requiring a standard sample dilution. 3) Inconsistent data may be missing from the Architect system. 4) Critical Error.
Z-0832-2007	LIFEPAK 20 Defibrillator/monitor	2 04-27-2007	08-05-2007	Medtronic Emergency Response Systems, Inc.	Whole Screen Lock up. LIFEPAK 20 defibrillators with software version 48 or version 52 may experience an intermittent timing issue during the power on sequence. This may lock up the device and cause a potential delay or prevention of shock treatment.
Z-0831-2007	CIC Pro System	2 01-24-2007	06-05-2007	General Electric Medical Systems Information Technology	Alarm and Robust problems: Two separate issues could occur with the CIC Pro system when used with telemetry. Each issue may cause a loss of audible alarm when operating system memory resources reach 170MB and/or B) the system may intentionally or unintentionally reboot.
Z-0852-2007	Pranabloc/Avray software	2 03-14-2007	06-08-2007	Varian Medical Systems Oncology System	Guidance Platform via DICOM RT: The software incorrectly computes the center of the CT volume resulting in a potential axial error ranging from 0.3 mm to 1.3 mm affecting both the target and the organs at risk (OAR) contours.
Z-0872-2007	GE Healthcare Inova 3100/3100 IC	2 02-26-2007	06-05-2007	General Electric Medical Systems, LLC	Measurement errors during the computation of vessel diameters while using the StenoViz Analysis software (also known as Quantitative Coronary Analysis function-QCA) using the automatic Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room) or in-room Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room).
Z-0859-2007	GE Healthcare Inova 4100/4100 IQ	2 02-26-2007	06-05-2007	General Electric Medical Systems, LLC	Measurement errors during the computation of vessel diameters while using the StenoViz Analysis software (also known as Quantitative Coronary Analysis function-QCA) using the automatic Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room) or in-room Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room).
Z-0871-2007	Inova 2100 IQ	2 02-26-2007	06-05-2007	General Electric Medical Systems, LLC	Measurement errors during the computation of vessel diameters while using the StenoViz Analysis software (also known as Quantitative Coronary Analysis function-QCA) using the automatic Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room) or in-room Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room).
Z-0709-2007	Precision Link Software	2 12-16-2006	05-25-2007	Abbott Diabetes Care Inc.	Measurement errors during the computation of vessel diameters while using the StenoViz Analysis software (also known as Quantitative Coronary Analysis function-QCA) using the automatic Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room) or in-room Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room).
Z-0815-2007	ECOTICE	2 06-01-2006	05-16-2007	GE Medical Systems	Measurement errors during the computation of vessel diameters while using the StenoViz Analysis software (also known as Quantitative Coronary Analysis function-QCA) using the automatic Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room) or in-room Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room).
Z-0766-2007	Medfusion 3500	2 02-03-2007	04-26-2007	Smiths Medical MD Inc	Measurement errors during the computation of vessel diameters while using the StenoViz Analysis software (also known as Quantitative Coronary Analysis function-QCA) using the automatic Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room) or in-room Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room).
Z-0702-2007	ABL800 Series FLEGO module	2 01-16-2007	04-06-2007	Radiometer America Inc	Measurement errors during the computation of vessel diameters while using the StenoViz Analysis software (also known as Quantitative Coronary Analysis function-QCA) using the automatic Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room) or in-room Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room).
Z-0704-2007	Instatrak 3000 Plus system	2 01-26-2006	03-30-2007	GE GE Medical Systems/Inche	Measurement errors during the computation of vessel diameters while using the StenoViz Analysis software (also known as Quantitative Coronary Analysis function-QCA) using the automatic Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room) or in-room Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room).
Z-0671-2007	LIFEPAK	2 03-05-2007	03-29-2007	Medtronic Emergency Response Systems, Inc.	Measurement errors during the computation of vessel diameters while using the StenoViz Analysis software (also known as Quantitative Coronary Analysis function-QCA) using the automatic Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room) or in-room Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room).
Z-0652-2007	Synges Dynamics	2 01-31-2007	03-28-2007	Siemens Medical Solutions USA Inc	Measurement errors during the computation of vessel diameters while using the StenoViz Analysis software (also known as Quantitative Coronary Analysis function-QCA) using the automatic Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room) or in-room Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room).
Z-0397-2007	PortaViz	2 10-02-2006	07-01-2007	Rhytec Inc.	Measurement errors during the computation of vessel diameters while using the StenoViz Analysis software (also known as Quantitative Coronary Analysis function-QCA) using the automatic Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room) or in-room Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room).
Z-0388-2007	Teumo APS 1	2 10-08-2006	02-01-2007	Terumo Cardiovascular Systems Corp	Measurement errors during the computation of vessel diameters while using the StenoViz Analysis software (also known as Quantitative Coronary Analysis function-QCA) using the automatic Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room) or in-room Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room).
Z-0372-2007	GE Centricity PACS RA1000 Workstation	2 01-12-2007	01-25-2007	GE Healthcare Integrated IT Solutions Systems Corp	Measurement errors during the computation of vessel diameters while using the StenoViz Analysis software (also known as Quantitative Coronary Analysis function-QCA) using the automatic Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room) or in-room Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room).
Z-0314-2007	Teumo APS 1	2 05-01-2004	12-21-2006	Terumo Cardiovascular Systems Corp	Measurement errors during the computation of vessel diameters while using the StenoViz Analysis software (also known as Quantitative Coronary Analysis function-QCA) using the automatic Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room) or in-room Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room).
Z-0312-2007	Teumo APS 1	2 05-01-2004	12-27-2006	Terumo Cardiovascular Systems Corp	Measurement errors during the computation of vessel diameters while using the StenoViz Analysis software (also known as Quantitative Coronary Analysis function-QCA) using the automatic Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room) or in-room Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room).
Z-0358-2007	APS III	2 10-05-2006	12-19-2006	St. Jude Medical CRMG	Measurement errors during the computation of vessel diameters while using the StenoViz Analysis software (also known as Quantitative Coronary Analysis function-QCA) using the automatic Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room) or in-room Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room).
Z-0298-2007	Identify	2 10-06-2006	12-19-2006	St. Jude Medical CRMG	Measurement errors during the computation of vessel diameters while using the StenoViz Analysis software (also known as Quantitative Coronary Analysis function-QCA) using the automatic Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room) or in-room Intra-Coronary/Intra-Vessel/Intra-Coronary (IC/IV/IC) calibration function on Inova Digital (located in control room).

Z-0802-04	Respect Software System	2 04-12-2004	07-20-2004	Baxter Healthcare Renal Div	There are software anomalies present that may increase the possibility of a medication error if the dialysis clinic software is not properly record or coordinate the administration of medications.
Z-0801-04	Baxter Renal Software Suite for Windows	2 04-12-2004	07-20-2004	Baxter Healthcare Renal Div	There are software anomalies present that may increase the possibility of a medication error if the dialysis clinic software is not properly record or coordinate the administration of medications.
Z-0812-04	Pinnacle3	2 03-03-2004	07-20-2004	ADAC Laboratories	A software defect relating to the motorized wedge functionality when using an Elekta linear accelerator can result in incorrect location data when using Elekta Leksell beams.
Z-0813-04	Pinnacle3	2 03-03-2004	07-20-2004	ADAC Laboratories	A software defect relating to the motorized wedge functionality when using an Elekta linear accelerator can result in incorrect location data when using Elekta Leksell beams.
Z-0814-04	Pinnacle3	2 03-03-2004	07-20-2004	ADAC Laboratories	A software defect relating to the motorized wedge functionality when using an Elekta linear accelerator can result in incorrect location data when using Elekta Leksell beams.
Z-0811-04	Pinnacle3	2 03-03-2004	07-20-2004	ADAC Laboratories	A software defect relating to the motorized wedge functionality when using an Elekta linear accelerator can result in incorrect location data when using Elekta Leksell beams.
Z-0730-04	Instrumentation Laboratory	2 03-04-2004	07-20-2004	Instrumentation Laboratory Co.	Software may cause instrument to emit beep causing reagent cartridge, which may affect patient test result.
Z-0737-04	Instrumentation Laboratory	2 03-04-2004	07-20-2004	Instrumentation Laboratory Co.	Software may cause instrument to emit beep causing reagent cartridge, which may affect patient test result.
Z-0837-04	CohereNet	2 11-17-2003	07-20-2004	CohereNet Inc letter Group	Software problem that may cause the instrument to remain on and emit laser radiation after the interface has been initialized.
Z-0727-04	PatentNet	2 02-27-2004	07-20-2004	General Electric Medical Systems Information Technology	Non-invasive blood pressure readings in cardiac station may be incorrect.
Z-0835-04	Cytomics MRP Software	2 02-13-2004	07-20-2004	Beckman Coulter Inc	Software anomaly: Sample ID and the Run Date may become incorrect. Subsequently run with results printed using the FlowPAGE print format will have the fixed Sample ID and Run Date rather than the correct Sample ID and Run Date.
Z-0835-04	CXP software Part No. 62389 version 1.0	2 02-13-2004	07-20-2004	Beckman Coulter Inc	Software anomaly: Sample ID and the Run Date may become incorrect. Subsequently run with results printed using the FlowPAGE print format will have the fixed Sample ID and Run Date rather than the correct Sample ID and Run Date.
Z-0827-04	Cytomics MRP Software Version 1754A 8641848317526 017258175322	2 02-13-2004	07-20-2004	Beckman Coulter Inc	Software anomaly: Sample ID and the Run Date may become incorrect. Subsequently run with results printed using the FlowPAGE print format will have the fixed Sample ID and Run Date rather than the correct Sample ID and Run Date.
Z-0832-04	Software Command for the Grammed 12/A Afterloader Control	2 02-05-2004	07-20-2004	Varian Medical Systems	Precision treatment software could potentially cause a healthcare practitioner to apply incorrect treatment regimen to patients undergoing brachytherapy.
Z-1034-04	Mammography X-ray system	2 05-21-2004	07-20-2004	Fujifilm Imaging Corporation	Existing software may allow image data to be truncated in the margin of the breast to processed patient images.
Z-1030-04	Radiance Head Localizer (HLL) Version B	2 05-25-2004	07-20-2004	Rejonics Inc.	Software may provide inaccurate coordinates and cause misalignment.
Z-0250-04	Solar	2 11-10-2003	12-18-2003	Solar Medical Systems Information Technology	Software may transmit patient records when transferring TRAM mode from Solar 9500 to other Solar monitoring systems without appropriate TRAM first.
Z-0255-04	Myris	2 09-25-2003	12-18-2003	Myris Healthcare Systems	Software defect. When orders are modified before the Roche manufacturer's instructions for using radiation treatment software may cause healthcare practitioners to misread the patient's treatment plan.
Z-0178-03	Vision (m)	2 10-31-2003	12-03-2003	Varian Brachytherapy	Software may allow patient ID in incorrect patient name may be transmitted with image to CyberKnife workstation.
Z-0084-04	Phispa Olysear LX	2 09-15-2003	11-06-2003	Phispa Medical Systems (Chonburi)	Due to a software anomaly an incorrect patient name may be transmitted with image to Olysear workstation.
Z-0085-04	Phispa Olysear LX	2 09-15-2003	11-06-2003	Phispa Medical Systems (Chonburi)	Due to a software anomaly an incorrect patient name may be transmitted with image to Olysear workstation.
Z-0082-04	Phispa Olysear LX	2 09-15-2003	11-06-2003	Phispa Medical Systems (Chonburi)	Due to a software anomaly an incorrect patient name may be transmitted with image to Olysear workstation.
Z-0007-04	Olympus Ultrasound System	2 08-19-2003	10-15-2003	Olympus America Inc.	Software malfunction: potential for simultaneous cross-linking of exam images to another patient's file.
Z-1200-03	Myria	2 07-23-2003	09-15-2003	Myria Healthcare Systems	Software defect. Data used in the diagnosis and/or treatment of a patient's illness are missing from the patient's report.
Z-1217-03	Laboratory System	2 07-22-2003	09-11-2003	Myria Healthcare Systems	Software design deficiency. If the dilution factor is added to the same result twice incorrect specimen values are reported.
Z-1220-03	Myria	2 07-24-2003	09-11-2003	Myria Healthcare Systems	Software Design Defect. Under certain conditions results are removed.
Z-1082-03	Myria	2 07-02-2003	08-07-2003	Myria Healthcare Systems	Patient files become mixed up due to a software defect.

Z-1235-04	3 Series Full Body Phlebotomy Smart Touch Control System Model #LNBH-2474	2 09-01-2003	07-30-2004	Davin Distributing Company	Software errors cause the unit to not deliver the prescribed therapy and do not allow the patient records to be saved.
Z-1233-04	3 Series Full Phlebotomy Smart Touch Control System Model #BSM-2474	2 09-01-2003	07-30-2004	Davin Distributing Company	Software errors cause the unit to not deliver the prescribed therapy and do not allow the patient records to be saved.
Z-1236-04	3 Series Full Phlebotomy Smart Touch Control System Model #BSM-2474	2 09-01-2003	07-30-2004	Davin Distributing Company	Software errors cause the unit to not deliver the prescribed therapy and do not allow the patient records to be saved.
Z-1234-04	3 Series Full Phlebotomy Smart Touch Control System Model #BSM-2474	2 09-01-2003	07-30-2004	Davin Distributing Company	Software errors cause the unit to not deliver the prescribed therapy and do not allow the patient records to be saved.
Z-1237-04	3 Series Full Phlebotomy Smart Touch Control System Model #BSM-2474	2 09-01-2003	07-30-2004	Davin Distributing Company	Software errors cause the unit to not deliver the prescribed therapy and do not allow the patient records to be saved.
Z-1012-04	HomeChoice & Yume	2 05-24-2004	07-20-2004	Baxter Healthcare Renal Div.	A software defect could result in a patient experiencing an overflow with software versions 8.5 and higher. The possibility of a software defect could result in the patient's blood volume to OFF and a change to the volume is made at the Verify I-DRAINXXX.MMI prompt.
Z-1013-04	HomeChoice PRO 6.5 Yume Plus	2 05-24-2004	07-20-2004	Baxter Healthcare Renal Div.	A software defect could result in a patient experiencing an overflow with software versions 8.5 and higher. The possibility of a software defect could result in the patient's blood volume to OFF and a change to the volume is made at the Verify I-DRAINXXX.MMI prompt.
Z-1065-04	Hitech HI VISION 6500 Self Autoexposer (AL)	2 05-07-2004	07-20-2004	Hitech Medical Systems America Inc	Due to a software defect, the image may be reported as "0" or left blank. The next sample will also be incorrectly reported for the same parameter.
Z-0887-04	DL 2000 Data Sawyer	2 04-20-2004	07-20-2004	Beckman Coulter Inc	Software defect. The type of results affected were replicate type results for a single sample transmitted within the same data stream.
Z-1067-04	DL 2000 Data Sawyer	2 02-14-2004	07-20-2004	Beckman Coulter Inc	Software malfunction. The humidor did not retain the official data stream.
Z-0929-04	Concha IV Plus	2 04-20-2004	07-20-2004	Hidden Respiratory Care Inc	Software malfunction. The humidor did not retain the official data stream.
Z-0604-04	Access	2 03-29-2004	07-20-2004	Beckman Coulter Inc	Software coding error may cause a fatal error message.
Z-0289-04	Pulox	2 11-14-2003	07-20-2004	Minolta Corp	Error in the internal software. When a pulse level is high or Error in the internal software. When a pulse level is high or Error in the internal software. When a pulse level is high or
Z-1095-04	Pulox	2 11-14-2003	07-20-2004	Minolta Corp	Error in the internal software. When a pulse level is high or Error in the internal software. When a pulse level is high or Error in the internal software. When a pulse level is high or
Z-0802-04	Magic View	2 04-01-2004	07-20-2004	Siemens Medical Solutions USA Inc	Realigning firm became aware of a potential problem through the Magic Navigator feature in the MagicView 300 V442A or V442B software are not being impacted accurately to create CT or MR images.
Z-1084-04	Millennium MLC Software Suite	2 05-27-2004	07-20-2004	Varian Medical Systems Inc	An anomaly occurs in the software suite (Millennium MLC Worksheet v 6.3 and 6.4 Integrated Treat v.6.5) when used in conjunction with the standard series MLC controller software v 1.0 or 6.1.

Z-085-03	Myers Laboratory System line 5.3 up to 5.3.2 with Anatomic Pathology	Myers Healthcare Systems	Software anomaly allows patient reports to contain incomplete data used for diagnosis or treatment.	2/06/16/2003	06/07/2003	Alcon Laboratories Inc.	Software anomaly allows patient reports to contain incomplete data used for diagnosis or treatment.
Z-0785-03	Alcon Ultramark	Myers Healthcare Systems	Software error could occur under specific circumstances show the line evaporation of elution volume and biased sample results for analysis protocols.	2/07/21/2003	08/05/2003	Alcon Laboratories Inc.	Software error could occur under specific circumstances show the line evaporation of elution volume and biased sample results for analysis protocols.
Z-084-03	MagNA Pure	Roche Diagnostics	A software bug in version 3.0 may result in prolonged mixing time evaporation of elution volume and biased sample results for analysis protocols.	2/08/26/2003	07/23/2003	Roche Diagnostics	A software bug in version 3.0 may result in prolonged mixing time evaporation of elution volume and biased sample results for analysis protocols.
Z-083-03	MagNA Pure 1000U version V6.0A	Siemens Medical Solutions USA Inc	Software issue	2/02/28/2003	07/19/2003	Siemens Medical Solutions USA Inc	Software issue
Z-087-03	Myers Laboratory System versions 5.2, 5.2.1 and 5.3	Myers Healthcare Systems	Software anomaly	2/06/10/2003	07/19/2003	Myers Healthcare Systems	Software anomaly
Z-1001-03	MagNA Pure LC	Roche Diagnostics	Potential for false negative patient results with software version software malfunction. May indicate that the image is flipped when it is not.	2/05/27/2003	07/15/2003	Roche Diagnostics	Potential for false negative patient results with software version software malfunction. May indicate that the image is flipped when it is not.
Z-084-03	X-Ray System	Siemens Medical Solutions USA Inc	software problem - erroneous results or system crashes	2/04/19/2003	07/08/2003	Siemens Medical Solutions USA Inc	software problem - erroneous results or system crashes
Z-0874-03	Atom Sema5	Siemens Medical Solutions USA Inc	software problem - loss of data	2/02/28/2003	07/02/2003	Siemens Medical Solutions USA Inc	software problem - loss of data
Z-0972-03	Atom Omega	Siemens Medical Solutions USA Inc	software problem - washbottle made changes without user input settings change without corresponding display change	2/04/01/2003	07/02/2003	Siemens Medical Solutions USA Inc	software problem - washbottle made changes without user input settings change without corresponding display change
Z-085-03	Echocardiograph	Siemens Medical Solutions USA Inc	software problem - software mismatch images and file names	2/05/07/2003	06/27/2003	Siemens Medical Solutions USA Inc	software problem - software mismatch images and file names
Z-085-03	Centurius Ventilator	Dräger Medical Inc.	Software Version 2.21 and 2.31 Software (for certain Region) may fail to interpret correctly additional characters in patient names.	2/05/12/2003	06/12/2003	Dräger Medical Inc.	Software Version 2.21 and 2.31 Software (for certain Region) may fail to interpret correctly additional characters in patient names.
Z-085-03	Fluorin	Fujfilm Medical System USA, Inc.	Imaging archive system software mismatch images and patient names.	2/03/11/2003	06/05/2003	Fujfilm Medical System USA, Inc.	Imaging archive system software mismatch images and patient names.
Z-0842-03	Perfusion CT	Canon USA Inc	Perfusion CT is displaying a higher gray and color values than normal. A software problem may occur when the gray and color values are normal. A software problem.	2/10/11/2002	05/16/2003	Canon USA Inc	Perfusion CT is displaying a higher gray and color values than normal. A software problem may occur when the gray and color values are normal. A software problem.
Z-0841-03	Leonardo	Siemens Medical Solutions USA Inc	Software anomaly. One client reported patient tests and results are deleted when separate orders are placed.	2/10/11/2002	05/16/2003	Siemens Medical Solutions USA Inc	Software anomaly. One client reported patient tests and results are deleted when separate orders are placed.
Z-087-03	Myers Laboratory System version 5.3	Myers Healthcare Systems	Software anomaly.	2/03/27/2003	05/09/2003	Myers Healthcare Systems	Software anomaly.
Z-084-03	Myers Laboratory System version 5.3	Myers Healthcare Systems	A software error can result in the delivery of a larger bolus of reagent than anticipated when the pump is programmed in a software failure to detect error in reference solution set-up can cause inaccurate results for Sodium Potassium and	2/03/27/2003	05/09/2003	Myers Healthcare Systems	A software error can result in the delivery of a larger bolus of reagent than anticipated when the pump is programmed in a software failure to detect error in reference solution set-up can cause inaccurate results for Sodium Potassium and
Z-0798-03	Deltec Cozmo	Deltec Inc	Software anomaly.	2/03/14/2003	05/09/2003	Deltec Inc	Software anomaly.
Z-0768-03	AGROSET	Abbott Laboratories Inc	Software anomaly. Graphical display emits results containing a less than (<) or greater than (>) or percent (%) symbol.	2/02/24/2003	05/01/2003	Abbott Laboratories Inc	Software anomaly. Graphical display emits results containing a less than (<) or greater than (>) or percent (%) symbol.
Z-0676-03	Myers Calculator/Data processing module for Medical Use (21 862.2100)Myers	Myers Healthcare Systems	Software anomaly. Some comments were not transferred when coming from the Reference Laboratory System file.	2/01/17/2003	03/26/2003	Myers Healthcare Systems	Software anomaly. Some comments were not transferred when coming from the Reference Laboratory System file.
Z-0676-03	Myers Laboratory System Version 5.3	Myers Healthcare Systems	Software anomaly. Patient results may be filled in the incorrect patient file.	2/02/19/2003	03/21/2003	Myers Healthcare Systems	Software anomaly. Patient results may be filled in the incorrect patient file.
Z-0676-03	Myers Laboratory System Version 5.3	Siemens Medical Solutions USA Inc	Software anomaly. English text code does not translate.	2/01/31/2003	03/05/2003	Siemens Medical Solutions USA Inc	Software anomaly. English text code does not translate.
Z-0626-03	Myers Laboratory System versions 5.2, 5.2.1 and 5.3	Siemens Medical Solutions USA Inc	Software system defect resulting in incomplete patient result information.	2/12/20/2002	01/30/2003	Siemens Medical Solutions USA Inc	Software system defect resulting in incomplete patient result information.
Z-0497-03	Myers Laboratory System version 5.3	Siemens Medical Solutions USA Inc	Software development logic defect.	2/12/06/2002	01/30/2003	Siemens Medical Solutions USA Inc	Software development logic defect.
Z-0422-03	Myers Laboratory System version 5.3	Siemens Medical Solutions USA Inc	Software anomaly.	2/11/15/2002	01/11/2003	Siemens Medical Solutions USA Inc	Software anomaly.
Z-0423-03	Myers Laboratory System versions 5.2 and 5.3	Siemens Medical Solutions USA Inc	Software vote out logic changed. Erroneous white blood cell counts.	2/11/22/2002	01/11/2003	Siemens Medical Solutions USA Inc	Software vote out logic changed. Erroneous white blood cell counts.
Z-0415-03	Myers Laboratory System version 5.3	Beckman Coulter Inc	Software anomaly.	2/11/08/2002	01/09/2003	Beckman Coulter Inc	Software anomaly.

Z-0417-03	COULTER LH 700 Series Hematology	Beckman Coulter Inc	Software.	2/11/08/2002	01/09/2003	Beckman Coulter Inc	Software.
Z-0418-03	COULTER LH 700 Series Hematology	Beckman Coulter Inc	Software.	2/11/08/2002	01/09/2003	Beckman Coulter Inc	Software.
Z-0418-03	COULTER LH 700 Series Hematology	Beckman Coulter Inc	Software.	2/11/08/2002	01/09/2003	Beckman Coulter Inc	Software.
Z-0222-03	Myers Laboratory versions 5.2 NOT 4.9-5.3 with NO CAPTURE Plus	Siemens Information Systems	Interfacing software systems have inconsistent character recognition characteristics.	2/10/24/2002	12/11/2002	Siemens Information Systems	Interfacing software systems have inconsistent character recognition characteristics.
Z-0319-03	Myers Laboratory Results Interface 1.4	Siemens Information Systems	Software coding error caused data formatting error.	2/10/28/2002	12/05/2002	Siemens Information Systems	Software coding error caused data formatting error.
Z-0024-03	Myers Laboratory version 5.2 with NO CAPTURE Plus	Siemens Information Systems	Software anomaly - software pages when desired on reports are not properly loaded with application software.	2/10/18/2002	12/05/2002	Siemens Information Systems	Software anomaly - software pages when desired on reports are not properly loaded with application software.
Z-1172-2005	Myers Laboratory version 5.2 with NO CAPTURE Plus	Siemens Information Systems	Medtronic has identified an issue related to installation or removal of the Lead Integrity Alert software in Entirety(R) and Entirety(R) Escudo software. The software will not install on a PC with the Lead Integrity Alert software installed. The software will not install on a PC with the Lead Integrity Alert software installed.	3/11/08/2008	04/08/2009	Medtronic Inc. Cordis Rhythm Management	Medtronic has identified an issue related to installation or removal of the Lead Integrity Alert software in Entirety(R) and Entirety(R) Escudo software. The software will not install on a PC with the Lead Integrity Alert software installed. The software will not install on a PC with the Lead Integrity Alert software installed.
Z-2322-2008	Co Patient Programmer	Medtronic Neuromodulation	Medtronic is retrieving four (4) patient programs that were not properly loaded with application software. The application software is not usable and can not communicate with a neurostimulation device. Without this functionality a patient programmer is not usable and can not communicate with a neurostimulation device.	3/05/12/2008	09/20/2008	Medtronic Neuromodulation	Medtronic is retrieving four (4) patient programs that were not properly loaded with application software. The application software is not usable and can not communicate with a neurostimulation device. Without this functionality a patient programmer is not usable and can not communicate with a neurostimulation device.
Z-2322-2008	Medtronic Patient programmer	Medtronic Neuromodulation	Medtronic is retrieving four (4) patient programs that were not properly loaded with application software. The application software is not usable and can not communicate with a neurostimulation device. Without this functionality a patient programmer is not usable and can not communicate with a neurostimulation device.	3/05/12/2008	09/20/2008	Medtronic Neuromodulation	Medtronic is retrieving four (4) patient programs that were not properly loaded with application software. The application software is not usable and can not communicate with a neurostimulation device. Without this functionality a patient programmer is not usable and can not communicate with a neurostimulation device.
Z-2389-2008	Philips	Philips Medical Systems	Software: If Weight Limits edited values will return to default values that were entered.	3/07/22/2008	09/18/2008	Philips Medical Systems	Software: If Weight Limits edited values will return to default values that were entered.
Z-1786-2008	AQUISON Advance 5.0 System	Siemens Medical Solutions USA Inc.	Measurements may result in distorted images and inaccurate measurements which could lead to a misdiagnosis.	3/03/21/2008	09/02/2008	Siemens Medical Solutions USA Inc.	Measurements may result in distorted images and inaccurate measurements which could lead to a misdiagnosis.
Z-1761-2008	Advance 5.0 System	Siemens Medical Solutions USA Inc.	Software issue may result in distorted images and inaccurate measurements which could lead to a misdiagnosis.	3/03/21/2008	09/02/2008	Siemens Medical Solutions USA Inc.	Software issue may result in distorted images and inaccurate measurements which could lead to a misdiagnosis.
Z-1309-2008	Phosphor System with Domains	National Biologics Corp	Software allows operators to override low line voltage error warning and store light intensity value.	3/02/19/2008	08/28/2008	National Biologics Corp	Software allows operators to override low line voltage error warning and store light intensity value.
Z-1071-2008	Diagnostic Ultrasound Unit	Hitech Medical Systems America Inc	Miscalculation reading. A software error in the firm's EUB-5500/VI VISION diagnostic scanning system causes a miscalculation of the left DSA/CCA ratio when using the Cavetti Marker Management. The new software version contained a magnification factor that above CAD markers misaligned with the identified indications. The marker area is miscalculated up to the identified indications. The marker area is miscalculated up to the identified indications.	3/02/25/2008	07/24/2008	Hitech Medical Systems America Inc	Miscalculation reading. A software error in the firm's EUB-5500/VI VISION diagnostic scanning system causes a miscalculation of the left DSA/CCA ratio when using the Cavetti Marker Management. The new software version contained a magnification factor that above CAD markers misaligned with the identified indications. The marker area is miscalculated up to the identified indications. The marker area is miscalculated up to the identified indications.
Z-1546-2008	The Science Full Field Digital Mammography System	Lorad A Hologic Inc.	Miscalculation. The calculation of the standard uptake value does not include the required calibration factor/decay correction factor. The resulting value is incorrectly published. The calibration error exists in both the software and the audit file.	3/02/28/2008	05/28/2008	Lorad A Hologic Inc.	Miscalculation. The calculation of the standard uptake value does not include the required calibration factor/decay correction factor. The resulting value is incorrectly published. The calibration error exists in both the software and the audit file.
Z-1644-2008	Enterprise Visual Medical Software	Emegon	Minor Temporary Freeze - A software compatibility issue may cause the blood glucose meter to cease operations and the software will not respond to the meter's status.	3/01/01/2008	05/28/2008	Emegon	Minor Temporary Freeze - A software compatibility issue may cause the blood glucose meter to cease operations and the software will not respond to the meter's status.
Z-1317-2008	One Touch Data Management Software 2.1.0	Lifescan Inc	Navigation has identified a potential safety issue with all versions of PEN View Software commonly used for analyzing patient images acquired with the PEN View product line.	3/12/18/2007	04/08/2008	Lifescan Inc	Navigation has identified a potential safety issue with all versions of PEN View Software commonly used for analyzing patient images acquired with the PEN View product line.
Z-0041-2008	PEM/rev	Naviscan PET Systems	Software anomaly. The PEEM product line incorporates an improvement in the software for the ABL700 and ABL800 Blood Gas Analyzers may allow for problem build up on the electrode membranes of blood gas analyzers. This condition can interfere with analysis results from one or more analyzers. The condition can interfere with analysis results from one or more analyzers.	3/08/01/2007	10/11/2007	Naviscan PET Systems	Software anomaly. The PEEM product line incorporates an improvement in the software for the ABL700 and ABL800 Blood Gas Analyzers may allow for problem build up on the electrode membranes of blood gas analyzers. This condition can interfere with analysis results from one or more analyzers. The condition can interfere with analysis results from one or more analyzers.
Z-1085-2007	ABL 800 FLEX analyzers	Radiometer America Inc	Software anomaly. The software may allow for problem build up on the electrode membranes of blood gas analyzers. This condition can interfere with analysis results from one or more analyzers. The condition can interfere with analysis results from one or more analyzers.	3/11/13/2006	07/24/2007	Radiometer America Inc	Software anomaly. The software may allow for problem build up on the electrode membranes of blood gas analyzers. This condition can interfere with analysis results from one or more analyzers. The condition can interfere with analysis results from one or more analyzers.
Z-0718-2007	CARD - Picom	Smiths Medical MD Inc.	Software anomaly. The software may allow for problem build up on the electrode membranes of blood gas analyzers. This condition can interfere with analysis results from one or more analyzers. The condition can interfere with analysis results from one or more analyzers.	3/01/19/2007	04/05/2007	Smiths Medical MD Inc.	Software anomaly. The software may allow for problem build up on the electrode membranes of blood gas analyzers. This condition can interfere with analysis results from one or more analyzers. The condition can interfere with analysis results from one or more analyzers.
Z-0380-2007	NicolaOne monitoring software 2.0	NicolaOne	Software anomaly. The software may allow for problem build up on the electrode membranes of blood gas analyzers. This condition can interfere with analysis results from one or more analyzers. The condition can interfere with analysis results from one or more analyzers.	3/08/25/2005	02/15/2007	NicolaOne	Software anomaly. The software may allow for problem build up on the electrode membranes of blood gas analyzers. This condition can interfere with analysis results from one or more analyzers. The condition can interfere with analysis results from one or more analyzers.

Z-0002-2007	Guidant Zoom Programming System KinexDX	3/05/19/2006	10-12-2006	Guidant Corporation	Final software build did not occur prior to shipment of select programmers.
Z-1035-06	SYNCHRON LX	3/04/06/2006	07-13-2006	Siemens Medical Solutions USA, Inc.	The radiologist's report comments may not be retained by the Correction feature (auto & manual) does not perform correctly for the glucose cup chemistry (GLUC) when sample type of 'Other' is selected. The ORDAC feature does function properly w/ serum plasma urine & CSF.
Z-0802-06	SYNCHRON LX	3/02/15/2006	05-25-2006	Beckman Coulter Inc	The ORDAC feature does function properly w/ serum plasma urine & CSF.
Z-0802-06	UniCell DVC 800/800	3/09/13/2006	05-25-2006	Beckman Coulter Inc	Correction (feature auto & manual) does not perform correctly for the glucose cup chemistry (GLUC) when sample type of 'Other' is selected w/ operating software versions 1.0 & 1.2. The ORDAC feature does function properly w/ serum plasma urine & CSF.
Z-0801-06	SYNCHRON LX 1735 Clinical Systems	3/09/15/2006	05-25-2006	Beckman Coulter Inc	It was confirmed that the ORDAC (Over Range Detection And Correction) feature (auto & manual) does not perform correctly for the glucose cup chemistry (GLUC) when sample type of 'Other' is selected w/ operating software version 4.5. Results for these samples could be elevated as much as twice the actual value. The ORDAC feature does function properly w/ serum plasma urine & CSF.
Z-0505-06	Medtronic Restore Neurostimulator	3/11/22/2005	05-23-2006	Medtronic Inc Neurological & Spinal Division	A limited number of Model 3771 Restore Neurostimulators have an incorrect internal memory parameter that caused the system to report a low battery status. This anomaly does not affect patient safety. The anomaly can be corrected by reprogramming the Restore Neurostimulator with specific software.
Z-0802-06	ARCHITECT B12 Reagent	3/02/08/2006	05-11-2006	Abbott Laboratories	Barcode labels for these two lots. As a result the ARCHITECT system software is unable to track how long a reagent kit has been stored onboard the ARCHITECT instrument.
Z-0803-06	Microarray Microarray Immunization GeneChip 3000x scanner with software	3/04/28/2005	05-06-2006	Affymetrix Inc.	Incorrect software version of instrument controller is not compatible with new configuration. This incorrect configuration may cause the instrument system to fail at start-up or during a run.
Z-0308-06	ARCHITECT i5600 System	3/12/08/2005	01-18-2006	Abbott Laboratories Inc	System software assigns a salibrator default volume of 2.0ul when field is left empty by operator at time assay parameters are set. Patient results could be affected if the volume required is less than 2.0ul.
Z-0777-06	View 12 ECG Module. It is a transportable multi-parameter ECG device	3/09/07/2005	11-23-2005	Datascope Corp	Software anomalies which include shut down while printing and incorrect interpretation reports of 12-Lead ECG data.
Z-0776-06	Patient Monitor Patient with abnormal detection or alarm. Monitor gain m.	3/09/07/2005	11-23-2005	Datascope Corp	Software anomalies which include shut down while printing invalid diastolic blood pressure display and incomplete and inaccurate interpretation reports of 12-Lead ECG data.
Z-1371-05	Regius	3/03/30/2005	08-13-2005	Konica Medical Imaging Inc.	One feature of the software on views of the device, which permits assembling three digital images into one image has occasionally had problems. Adjusting the three image assembly.
Z-0807-05	Programming for Polytiter Polytiter Immunofluorescence System	3/09/24/2004	05-10-2005	Disoron Inc.	A problem with software for the Polytiter Immunofluorescence Polytiter Calibration Y-axis are re-centered or changed (including values changed to unacceptable values) after the initial curve has been generated if the 'refresh' button has not been pressed. The error may appear valid, however erroneous results may occur.
Z-0702-05	DiScan Software	3/05/20/2004	04-13-2005	Disoron Inc.	When software was updated for the Washer program of the Bio-Tek Automated Microplate Washer Model EL500 the software version 2.00 was replaced by version 2.01 of the wash program which contains errors added.
Z-0702-05	DiScan Software	3/04/12/2004	04-13-2005	Disoron Inc.	The software program written for use in the automated microtiter plate reader (Bio-Tek EL500) for use with the Programmable Washer Model EL500 software version 2.00. The software program did not include the Calibrator Zero OD specification (STOD=1.800) as specified in the product insert.
Z-0206-05	CSV software for FCS200	3/11/02/2004	11-30-2004	Beckman Coulter Inc	Incorrect sample identification can be displayed and printed on the Routine Panel Report due to a software defect.
Z-0207-05	DL2000 Data Collector Software	3/11/05/2004	11-30-2004	Beckman Coulter Inc	Capability of reporting an incorrect result occur due to a software anomaly.
Z-0209-05	Version 6.4.108 1.1 Operating software for FCS200 CytometerPart	3/08/02/2004	11-30-2004	Beckman Coulter Inc	Software anomaly.

Z-0631-05	Excimer (s) VANTAGE P2 & P3 Magnetic Resonance Imaging System	3/09/16/2004	11-02-2004	Toshiba American Med Sys Inc	Scanned images are acquired at a position that is shifted relative to the intended position in the slice direction due to a software anomaly.
Z-1036-04	Data Manager Fujifilm IP	3/11/05/2005	07-26-2004	Beckman Coulter Inc	Software anomaly allows results to be archived prior to validation as to be uploaded to the lab information system.
Z-0993-04	ESCALO Magnetics	3/05/05/2004	07-20-2004	Fujifilm Medical System USA, Inc.	Software: Incorrect measurement of object within a CR image
Z-0637-04	Reconex System Software	3/05/06/2004	07-20-2004	Toshiba American Med Sys Inc	Software anomaly.
Z-0818-04	ARCHITECT	3/03/19/2004	07-20-2004	Abbott Laboratories Inc	When using a LIS the software system will send up a test result of up to 20 characters although the field is set to display only 16 characters (before RS-232C format).
Z-0744-04	Acuson Cervical Doppler	3/02/02/2004	07-20-2004	Siemens Medical Solutions USA Inc	Software problem - mode does not appear on screen
Z-0646-04	Toshiba	3/01/27/2004	07-20-2004	Siemens Medical Solutions USA Inc	Software anomaly causes image slices to be in incorrect order.
Z-1079-04	OrionMD	3/08/21/2004	07-20-2004	Adas Labs	Software problems may cause the detector head to drift unexpectedly.
Z-0531-04	Medtronic 7311 Version 5.08 Solutions	3/01/28/2004	02-10-2004	Medtronic Minimed	A minor software anomaly results in an error in the calculation of the average glucose range that appears on one of the reports available in the model 7311 software.
Z-0527-04	Onepass Nuclear Medicine	3/01/16/2004	02-10-2004	CVI Technology Partners	Due to fluctuations in the operating software the acquired scan may not be processed properly.
Z-0285-04	Minimed Model 7311 Version 5.08 Solutions	3	12-24-2003	Medtronic Minimed	Accessory software fails to report certain reports following download of data from 712 pump.
Z-1142-03	ARCHITECT	3/12/25/2003	08-21-2003	Abbott Laboratories Inc	ICT assays run using a manual dilution will not be calculated correctly by the software.
Z-1146-03	Immunoassay System Technical 1 Part number 387851	3/06/16/2003	08-21-2003	Beckman Coulter Inc	Defective software media distributed with upgrade software may cause installation failure and systems lock.
Z-1138-03	Immucite 2000 Immunoassay Software version 2.6 was to be installed on running 2.5b.	3/06/13/2003	08-20-2003	DPC Corp	Version 2.6 software was released however it will not properly handle adjustment slopes.
Z-1126-03	Olympus ImageManager	3/03/05/2003	08-12-2003	Olympus America Inc.	Software defect; potential under certain circumstances to prevent normally operating images that have been updated to match the instrument version.
Z-1053-03	Maya Laboratory Software Version 5.3 up to 5.3.2 with LabAccess Workstation Leonardo	3/06/23/2003	08-07-2003	Maya Healthcare Systems	Software defect.
Z-1068-03	Workstations Leonardo	3/02/26/2003	08-07-2003	Siemens Medical Solutions USA Inc	software problem
Z-1067-03	MR Systems	3/02/28/2003	08-07-2003	Siemens Medical Solutions USA, Inc	software problem
Z-1069-03	Leonardo Workstations	3/02/26/2003	08-07-2003	Siemens Medical Solutions USA, Inc	software problem
Z-0665-03	Acuson	3/03/31/2003	05-22-2003	Siemens Medical Solutions USA, Inc.	The product has a software condition in that the surface temperature of the transducer may reach above the thermal limit.
Z-0664-03	Acuson	3/03/31/2003	05-22-2003	Siemens Medical Solutions USA, Inc.	The product has a software condition in that the surface temperature of the transducer may reach above the thermal limit.
Z-0604-03	Maya Commercial Laboratory Information System version 3.4.1	3/03/24/2003	05-09-2003	Maya Healthcare Systems	Software logic error.

Z-4805-03	COULTER Prophus 3rd Printing and Duplicating Division 10000 Software	3/02-28-2003	01-09-2003	Beckman Coulter, Inc	Software problem may cause the instrument to skip the probe-wash step before processing different reagents.
Z-0727-03	Siemens Medical Solutions USA, Inc.	3/02-10-2003	04-16-2003	Siemens Medical Solutions USA, Inc.	ICON 3.5 software does not apply flood corrections during whole-body, SPECT, SPECT-CT, and PET scans with multiple bed positions.
Z-4865-03	LH 700 Series Hematology Analyzers 6805602 6805603 6805604	3/12-27-2002	03-21-2003	Beckman Coulter, Inc	Incorrect Hemoglobin result can be reported at software version 2A and higher.
	No reported patient injuries or illnesses for the use of this device in conjunction with this device.				
	The primary use of a Live Gate is for the intentional removal of unwanted events such as debris. The Live Gate is used to identify and remove debris. The Live Gate will not be stored to the final listmode file this reducing the data set size.				
	The software error associated with the excluded sample appears as "Excluded Sample" in the sample list. The sample will be excluded from further processing.				
	A. Self-Survey Field Correction GSI Aurora units with version 2.6 software may mislabel Auditory Evoked Potential (AEP) waveform identification of the stimulus as "When using 2.6 software in split-screen mode". The software update adds the algorithm (Sdgsdgs) for PATWAY anti-HERZ/tau (4BS) antibody to the VMS system.				
	Nephelometry Standardized Uptake Value (PENSUV) and distance measurements for the product are not supported. The error message "If a zoomed image has been opened measurement tools are used and this applies only" may occur when performing the ET-Mumps IgG assay on the ET-Max 3000 automated platform. The error message "The error message 'If a zoomed image has been opened measurement tools are used and this applies only' may occur when performing the ET-Mumps IgG assay on the ET-Max 3000 with the ET-Mumps IgG assay as the second assay on a combined plate assay." may occur when performing the ET-Mumps IgG assay on the ET-Mumps IgG assay as the second assay on a combined plate assay. When Quality Assurance failures warnings are missing from a patient's report, abnormal results are reported. The error message "The error may cause the loss of peripheral image information when there is a difference between the dimensions of the image matrix and the display segment."				
	The error may cause the loss of peripheral image information when there is a difference between the dimensions of the image matrix and the display segment.				
	This error may cause the loss of peripheral image information when there is a difference between the dimensions of the image matrix and the display segment.				

FDA が iPhone で動作するソフトウェアを医療機器と認定したことに対して“When is an iPhone a Medical Device?”なる記事が載った FDC reports で発行されたようです。

その部分を抜粋した内容を下記に添付します。

内容的には、「CTG の表示装置が iPhone のアプリとして FDA 認可を受けているが、iPhone 自体は一般装置なので、医療機器ではない。但し、アップルが 医療ソフトを含んだ状態で出荷した場合は iPhone も医療機器となる。」

雑誌名：

“The Silver Sheet”

Medical Device Quality Control Reports

Vol. 13, No. 4 April 2009

内容：p11 から抜粋

The same applies to Apple's iPhone. San Antonio-based AirStrip Technologies received FDA clearance April 6 to market its AirStrip OB application for use on the iPhone.

Obstetricians can use the AirStrip software to remotely access real-time data for a mother and baby, including heart tracings and contraction patterns.

Further, Johnson & Johnson subsidiary LifeScan has produced a prototype system for the iPhone that aids patients with diabetes management.

However, Apple probably won't need to worry

about meeting FDA regulations.

"If an iPhone is sold as a general-purpose mobile phone and a hospital decides to use it for some medical purpose, it would not be a medical device," Eagles says. But if Apple "marketed it for a purpose that met the definition of a medical device, such as a nurse call station, then it would be regulated as a medical device."

CASE STUDY
事例研究

REPORT
レポート

NEWS
ニュース

INFORMATION
インフォメーション

▼ ニュース

NEWS

▶ 記事一覧へ

ソフトバンクテレコム、遠隔医療などでの iPhone の業務事例公開

ソフトバンクテレコムは2009年10月14日、医療・教育分野におけるiPhone利用事例を公開した。遠隔での画像診断や在宅医療などでの活用が始まっているという。ソフトバンクテレコムの宮内謙代表取締役副社長兼COO(最高執行責任者)は「単なるインターネット端末としてではなく、仕事に直結する使い方をする企業や団体が増えている」と分析する。



医療画像を iPhone で閲覧する

医療分野では、放射線を使った医療画像の診断に iPhone を使う共同研究を実施していることを明かした。鹿児島県霧島市にある霧島市立医師会医療センターなど4医療機関が、IT企業ジェイマックスシステムを共同で実施している。院内に専門の診断医がいなくても、iPhoneに画像を送って遠隔で診断可能にした(写真)。

在宅利用でも使われている。都内で桜新町アーバンクリニックなどを運営する医療法人社団プラ

タナスは、病気などで通院が困難な患者の在宅医療を担当する医師に iPhone を持たせ、情報共有に取り組んでいる。「ノート PC よりもスピーディに情報を共有できる」と桜新町アーバンクリニックの遠矢純一郎氏は話す。

ファイル共有サービス「Dropbox」や「Google カレンダー」を使って患者情報やスケジュールを共有するほか、画像や映像を使った処置支援にも取り組んでいる。「患者に気管カニューレと呼ばれるチューブを挿入する際に、患者によっては斜めに入れたほうが良いなど、注意すべき点がある。それを動画や画像で共有する」(遠矢氏)。

青山学院大学や日本電子専門学校は、教育分野で iPhone を使う。青山学院大学は講義に必要な資料を、学生が持つ iPhone 向けに配信している。同大学は 2009 年 5 月に、iPhone を教員と学生 550 人に配布済みである。資料データの配信システムには、インフォテリアの iPhone 向けデータ配信サービス「Handbook」を採用した。

日本電子専門学校は 2010 年 4 月に「ケータイ・アプリケーション科」を新設し、教育内容の一つとして iPhone 向けアプリケーション開発を取り上げるほか、授業の資料配付や資格検定の教育などにも利用するという。(ITPro)

▲ PAGETOP

© 2006-2009 Nikkei Business Publications, Inc. All Rights Reserved

TITLE:ソフトバンクテレコム、遠隔医療などでの iPhone の業務事例公開：日経メディカル オンライン

DATE:2009/12/24 09:25

URL:<http://medical.nikkeibp.co.jp/leaf/all/special/it/news/200910/512899.html>

企業調査報告 ソフトウェアの規制に関する検討

アンケート実施から分析まで

財団法人 先端医療振興財団
クラスター推進センター 医療機器サポートプラザ
総括・中小企業相談担当 調査役 吉川 典子

1 調査背景

医療機器の研究開発に関する相談業務に従事しているが、ソフトウェアに関する相談を持ち込む相談者の背景を見ていると、企業規模が小さいことが多いことが判明した。こうした企業から、ざっくりばらんな意見を聴取したところ、ソフトウェアが単独では、医療機器として扱われていないことについて、賛成意見と反対意見に二分されていた。さらに、業界団体への加盟がないことも多く、なかなか意見を出す機会もないことも判明した。こうしたことから、平成20年度報告に続き、筆者のいる神戸医療産業都市関連以外の企業にも対象を広げ、調査を行うこととした。

このような背景から、調査対象者の選定については、いわゆる医療機器が関連する学会展示会を中心とはせず、医療機器やものづくりに関する産業系の展示会に出展しているようなところを対象とした。

別添のとおりアンケート用紙を送付し、得られたご回答をもとに、扱っているソフトウェアの対象範囲や、製品開発のきっかけ、規制に関する意見を知り、実態を明らかにすることとした。なお、アンケート用紙の作成にあたっては、平成20年において、神戸医療産業都市エリア内の企業からいただいた自由意見をもとに設計を行った。

(参考) アンケート送付先の抽出

2段階にて抽出し、
神戸医療産業都市構想関連企業から、取扱企業をピックアップする

- 1 進出企業リスト
- 2 地元企業に関するデータブック
- 3 産学連携コンソーシアム

大規模調査のための資料

- 4 2008国際医用画像総合展
- 5 CADM&CAD
- 6 日本画像医療システム工業会 JIRA
- 7 メディカルクリエーションふくしま 出展者資料
- 8 岐阜大垣地域ロボティッククラスター

合計として100企業を選択した。


2 アンケート結果のまとめ

2-1 回答者の像

回答者属性

大学	2
公設研究所	1
医療機関	0
企業	22

企業サイズについては、下記のような回答が得られた。資本金としてのサイズと、人数としてのサイズである。




なお、このうち、企業22社のうち、何らかの業界団体への所属があるところは11である。ほとんどがJIRAへの所属である。地元商工会のものもあった。

2-2 取り扱い状況

取り扱う製品について、大きく、画像診断、治療計画、診療支援、その他と分類して、回答を求めた。製品群の選定にあたっては、複数回答を受け入れており、いくつかの該当がある企業もあった。画像診断、診療支援、その他で、ほぼ3分の2の結果となった。





その他としての事例は、データの授受ソフトウェア、座標表示、計測といった基礎的な

処理のものが中心である。いくらかは、カテゴリーの選定に苦慮した結果、その他を選んだのかもしれない。




それぞれの製品群別の、扱い状況の結果を示す。

画像診断




左上の円は、扱うモダリティの種類を回答している。また、左下は、扱うデータの対象を示している。右上は、ハードウェアとの組み合わせの確認のため、適用する機種の特定制をしているか、何らかの規格に適合していることを求めているかどうかについての回答である。右下においては、規格の対応を行っているかについてであるが、半数が適合している規格があり、DICOMであった。

治療計画



左上の円は、扱うモダリティの種類を回答している。治療計画を行うことから、元となるデータソースが、計画をするに値するかどうかということに左右されるため、MRI、X線CTに集中している。また、左下は、扱うデータの対象を示している。動物分野も対象としている回答が目立つ。右上は、ハードウェアとの組み合わせの確認を行っているかについてであるが、適用する機種の特定をしているか、何らかの規格に適合していることを求めているかどうかについての回答である。右下においては、対応している規格についてであるが、すべてが対応し、DICOMであった。

診療支援



左上の円は、扱うモダリティの種類を回答している。複数回答を可能としている。診療支援のためのものであり、様々なデータを基に診療を行うことを反映して、非常に多くの種類の回答があった。また、左下は、扱うデータの対象を示している。右上は、ハードウェアとの組み合わせの確認をしているかにおいて、適用する機種の特定をしているか、何らかの規格に適合していることを求めているかどうかについての回答である。三分されており、診療支援内容によっては、全く限定していないものもあった。右下においては、そのソフトウェアが規格に適合しているかについてであるが、全数が適合させている規格がないという回答であった。